

VT-L02-107-33
 contract no.

photo no.

1-14-88 2:08
 date time am/pm

WEST
 view direction

description: PICTURE
OF THE PLANT
SCALE PRIOR TO BLAST
 BOYLE



VT-L02-107-33
 contract no.

photo no.

1-14-88 2:00
 date time am/pm

SOUTH
 view direction

description: PICTURE OF
CONTROL
BUILDING (PRE BLAST)
 BOYLE



VT-L02-107-33
 contract no.

photo no.

1-14-88
 date time am/pm

EAST
 view direction

description: SLUDGE
BUILDING AREA BEFORE
BLAST #1
 BOYLE





VT-602-107-33
contract no.
~~1-14-88~~
photo no.
1-14-88
date time am/pm
view direction
description: SITE PAVED
BEFORE BLAST
1
BOYLE



VT-602-107-33
contract no.

photo no.
1-14-88
date time am/pm

view direction

description: SITE

SITE SHOTS BEFORE

BLAST
BOYLE





VT-L02-107-33
contract no.

photo no.
1-14-88

date time am/pm
NORTH-EAST
view direction

description: SITE SHOT
AND CITY BURSTING
INSPECTOR-PreCAST
BOYLE



VT-L02-107-33
contract no.

photo no.
1-14-88

date time am/pm
NORTH
view direction

description: POWDER MILL
PREPARING FOR
PRECAST
BOYLE



VT-L02-107-33
contract no.

photo no.
1-14-88

date time am/pm
SOUTH-EAST
view direction

description: DRILLED
HOLES STOPPED WITH
PAPER-BASE PILE
BOYLE

VT-L02-107-33
contract no.

photo no.
1-14-88
date time am/pm

NORTH
view direction

description: JOHN McLAUGHLIN
AND POWDERMAN
RUNNING WIRE
BOYLE



VT-L02-107-33
contract no.

photo no.
1-14-88
date time am/pm

NORTH
view direction

description: LOCATION
OF BLAST #1
BOYLE



VT-L02-107-33
contract no.

photo no.
1-14-88
date time am/pm

view direction

description: POWDER
FOR BLAST
BOYLE





VT-102-107-33
 contract no.

 photo no.
1-14-88
 date time am/pm
NORTH
 view direction

 description: BASE
COVERING BASE
1 AREA
BOYLE BEFORE BLAST



VT-102-107-33
 contract no.

 photo no.
1-14-88
 date time am/pm
NORTH
 view direction

 description: FENCE
COVERING & BASE
BEFORE BLAST
BOYLE



VT-102-107-33
contract no.

photo no.

1-14-88
date time am/pm

ALL THREE
view direction

description: BLAST

AREA BEFORE

BLAST
BOYLE





VT-102-107-33
contract no.

photo no.
1-14-88
date time am/pm

SOUTH WEST
view direction

description: END OF
BLAST #2 BEFORE
BLAST
BOYLE



VT-102-107-33
contract no.

photo no.
1-14-88
date time am/pm

NORTH EAST
view direction

description: Looking
Down FROM END OF
BLAST BEFORE BLAST
BOYLE



VT-102-107-33
contract no.

photo no.
1-14-88 2:18
date time am/pm

WEST
view direction

description: BLAST #2
OCCURRING.
BOYLE

VT-LO2-107-33
contract no.

photo no.

1-14-88 2:14
date time am/pm

EAST
view direction

description: BEAST #1

CONTINUING 3/2

SEE PREVIOUS PICTURE
BOYLE



VT-LO2-107-33
contract no.

photo no.

1-14-88
date time am/pm

EAST
view direction

description: AFTER

BEAST #1 IS OVER

BOYLE



VT-LO2-107-33
contract no.

photo no.

1-14-88
date time am/pm

NORTH
view direction

description: BEAST #2-

AFTER BEAST - BASE

PILE
BOYLE





VT-L02-107-33
contract no.

photo no.

1-14-88
date time am/pm

NORTH
view direction

description: THE N. END
OF THE BLAST AFTER
BLAST
BOYLE



VT-L02-107-33
contract no.

photo no.

1-14-88
date time am/pm

NORTH
view direction

description: SPOIL ON
SLOPE FROM BLAST
#1
BOYLE



VT-L02-107-33
contract no.

photo no.

1-14-88
date time am/pm

SOUTH EAST
view direction

description: SPOIL FROM
BLAST #2 KNOCK OVER
FENCE
BOYLE

VT-102-107-33
contract no.

photo no.

1-15-88

date time am/pm

WEST

view direction

description: SLIGHT

PICTURE THE

DAY AFTER PAST #1
BOYLE



VT-102-107-33
contract no.

photo no.

1-20-88

date time am/pm

view direction

description: PAST #2

LAYOUT WINDING

BOYLE





VT-102-107-33
contract no.

photo no.

1-20-88
date time am/pm

NORTH EAST
view direction

description: PLACING
BASE OVER BLAST #2

AREA
BOYLE



VT-102-107-33
contract no.

photo no.

1-20-88
date time am/pm

EAST
view direction

description: BLAST #2
AREA AFTER BLAST
AFTER BASE REMOVED

BOYLE



VT-102-107-33
contract no.

photo no.

1-21-88
date time am/pm

EAST
view direction

description: EXCAVATED
TRENCH SECTION TO
CHECK BLAST RESULTS

BOYLE

VT-202-107-33
 contract no.

photo no.

1-21-88
 date time am/pm

NORTH
 view direction

description: NARROW
TRENCH - BLAST #2

RESULTS
 BOYLE



VT-202-107-33
 contract no.

photo no.

~~1-21-88~~ 1-29-88
 date time am/pm

NORTH WEST
 view direction

description: PRE BLAST
SITE PHOTO FOR BLAST
#3

BOYLE





VT-102-107-33
contract no.

photo no.

1-29-88
date time am/pm

NORTH EAST
view direction

description: PRE BURST
#3 - SIGHT PHOTO

BOYLE



VT-102-107-33
contract no.

photo no.

1-29-88
date time am/pm

SOUTH EAST
view direction

description: PRE
BURST #3 - SHOWS
CONTROL BUILDING

BOYLE



VT-102-107-33
contract no.

photo no.

1-29-88
date time am/pm

NORTH EAST
view direction

description: PRE - BURST
#3 FREE OF

HILL
BOYLE

VT-L17-109-01
 contract no.

photo no.

1-29-88
 date time am/pm

EAST
 view direction

description: FIRST
HALE OF LINE - SPLIT
BLASTS.
 BOYLE



VT-L02-102-33
 contract no.

photo no.

1-29-88
 date time am/pm

EAST
 view direction

description: 2nd HALF
OF LINE - BLAST
SPLIT BLAST
 BOYLE





VT-102-107-33
contract no.

ALL THREE
photo no.

1-29-88
date time am/pm

~~EAST~~ WEST
view direction

description: BLAST

SEQUENCE IN

ORDER (FACE)

BOYLE

VT-402-107-33
 contract no.
ALL THREE
 photo no.
1-29-88
 date time am/pm
EAST
 view direction
 description: BLAST
SEQUENCE CONTINUED
(FACE)
 BOYLE





VT-02-107-33
 contract no.

photo no.

1-29-88
 date time am/pm

view direction

description: AFTER
FINAL BAST
SURVIVAL LINE HOLES
BOYLE

VT-02-107-33
 contract no.

photo no.

2-22-88 9:00
 date time am/pm

~~EAST~~ WEST
 view direction

description: SITE
SHOT (WEEK)

BOYLE